	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comm ents
1	BRS	L1	9206 8	arınder or arılı		2007/06/ 14 15:18	
2	BRS	L2	I .	(sensor or detector).ab.	i	2007/06/ 14 15:19	
3	BRS	L3	3714 11	(pressure or force).ab.	USP AT	2007/06/ 14 15:19	
4	BRS	L4	596	1 and 2 and 3	USP AT	2007/06/ 14 15:19	

	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comm ents
1	BRS	L1	1	"5014793".pn.	ĺ	2007/06/ 14 14:54	

	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comm ents
1	BRS	L1	7383 2	tool.ab.	USP AT	2007/06/ 14 13:50	
2	BRS	L2	3714 11	(pressure or force).ab.	USP AT	2007/06/ 14 13:51	·
3	BRS	L3	1	(contact or surface).ab.	USP AT	2007/06/ 14 13:51	
4	BRS	L4	7218 19	motor	USP AT	2007/06/ 14 13:51	
5	BRS	L5	1112	11 and 2 and 3 and 4	USP AT	2007/06/ 14 13:52	
6	BRS	L6	9206 8	drill or grinder	USP AT	2007/06/ 14 13:52	
7	BRS	L7	321	5 and 6	USP AT	2007/06/ 14 13:52	

,	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comm ents
1	BRS	L1	6397 5	tool.ab.		2007/06/ 14 12:48	
2	BRS	L2	١.	contact near3 pressure	USP AT	2007/06/ 14 12:48	
3	BRS	L3	1620	1 and 2	USP AT	2007/06/ 14 12:48	
4	BRS	L4	6446 31	display\$4	USP AT	2007/06/ 14 12:48	
5	BRS	L5	172	3 and 4	USP AT	2007/06/ 14 12:48	